U.S. Department of Transportation

United States Coast Guard

LOCAL NOTICE TO MARINERS

COASTAL WATERS FROM EASTPORT, MAINE TO SHREWSBURY, NEW JERSEY

WEEKLY SUPPLEMENT

** Electronic Bulletin Board Service: (703) 313-5910 ** 300 to 28.8 bps, 8 data bits, no parity, 1 stop bit ** NIS watchstander, 24 hours a day at (703) 313-5900 **

** INTERNET ADDRESS **
HTTP://www.navcen.uscg.mil
OR
FTP://ftp.navcen.uscg.mil

Weekly supplemental editions contain new information only available following the monthly edition. NOTE: Chart corrections and Light List changes appear only once each. A complete listing of current discrepancies and temporary changes appear in the monthly issue, LNM 20/97. Subscription to this weekly publication is free. If you have questions about the LNM or wish to be on the mailing list, contact:

COMMANDER, FIRST COAST GUARD DISTRICT (oan) 408 Atlantic Avenue, Boston, Massachusetts 02110-3350

Telephone (Day): 1-800-848-3942. To order LNM: Ext. 8335 (After 4:30 p.m. Ext. 7722) 24 Hour FAX: (617) 223-8073

Coast Guard's Customer Infoline (8:00 a.m. - 4:00 p.m.): 1-800-368-5647. Hearing impaired (TDD) 1-800 689-0816

All bearings are in degrees TRUE - All times are in Local Time unless otherwise noted.

NOTE: A vertical line in the RIGHT MARGIN of sections I, V, VI, VII indicates new information.

BROADCAST NOTICE TO MARINERS

The following Broadcast Notice to Mariners (BNM's) have been issued since last week:

First District CG1-0269 to 0279 Group Boston BOS-0053 to 0054

Group Long Island Sound LIS-0060 to 0062

Group Moriches MOR-0034 to 0034

Group New York NEW-0115 to 0117

Group Portland POR-0038 to 0041

Group Southwest Harbor SWH-0046 to 0046

Group Woods Hole WHO-0074 to 0076

I SPECIAL NOTICES This section contains information of Special concern to the Mariner.

NATIONAL PARK SERVICE - REGULATORY MARKERS - SANDY HOOK, NJ

The United States Department of Interior, National Park Service, has installed regulatory marker buoys in the bay and ocean waters around Sandy Hook, NJ. In position 40 25' to 40 28' latitude and 73 58' to 74 01' longitude. The buoys indicate No Wake Zones and areas closed to boat traffic. Spermaceti Cove, on the bayside at 40 25' 30" and 73 59' 00" is closed to all boat traffic due to wildlife management activities. Boaters are requested to remain outside of the buoys along the oceanside beaches due to high numbers of swimmers using the area. These buoys will remain in place until 10/31/97, at which time they will be removed for the winter season. For more information contact (908) 872-5933.

Charts: 12324, 12327 LNM 23/97

II DISCREPANCIES This section lists all discrepancies to Aids to Navigation reported and corrected since the last published list. A discrepancy is a change in the status of an aid to navigation that differs from what is published and or charted.

DISCREPANCIES (since last week)

LLNR Name of Aid Status Chart BNM LNM affected Ref. Ref.

		_		
00390 23/97	THE GRAVES LT	LT DIM	13270	CG1-0274-97
01180 23/97	BROTHERS PASS BB 1	LT EXT	13326	WHO-0073-97
01955 0046-97	PULPIT LDG DBN 3 23/97	DBN IMCH		13322 SWH-
04950 0039-97	DUCK ROCKS BB 5 23/97	FS IMCH		13302 POR-
19750 0076-97	GREAT SALT POND BKW LT 4 23/97	FS INOP		13217 WHO-
21165 23/97	KIMBERLY REEF LHB KR	FS INOP	12354	LIS-0061-97
27305 23/97	ROOSEVELT IS REEF LB B	LT EXT	12335	NEW-0117-97

DISCREPANCIES CORRECTED

LLNR Name of Aid Status Chart BNM LNM affected Ref. Ref.

			-		
00450	TWENTY-ONE FOOT LWB 21	RELIGHTED		13269	BOS-
0050-97 00955 0045-97	22/97 ST. CROIX RIV LB 13 23/97	WATCHING PROPERI	WATCHING PROPERLY		SWH-
01275 0029-97	BAY LEDGES BY 2 13/97	WATCHING PROPERI	_Y	13326	SWH-
01565 22/97	PLEASANT RIV BY 14	RESET ON STATION	13324	SWH-0	040-97
02925 0044-97	EGGEMOGGIN LBB EG 22/97	WATCHING PROPERI	_Y	13309	SWH-
03805 0041-97	HURRICANE SND BY 15 22/97	WATCHING PROPERI	_Y	13305	SWH-
04525 0039-97	HALIBUT RK BY 2B 22/97	WATCHING PROPERI	_Y	13303	SWH-
08485 23/97	PISCATAQUA RIV LB 6	RESET ON STATION	13285	POR-0	038-97
09480 23/97	ESSEX BAY ENT LBB 1	RELIGHTED	13279	BOS-0	054-97

PLYMOUTH BAY CH LB 3	RELIGHTED	13253	BOS-0051-97
SESUIT HBR E JTY DBN 3	WATCHING PROPERL	_Y	13250 WHO-
SESUIT HBR W JTY LT 2	WATCHING PROPERL	_Y	13250 WHO-
22/97	DELICUTED	10075	LIS-0060-97
CONNECTION RIVER 14	RELIGHTED	12375	LIS-0060-97
SANDY HOOK LT	RELIGHTED	12327	NEW-0115-97
	SESUIT HBR E JTY DBN 3 22/97 SESUIT HBR W JTY LT 2 22/97 CONNECTICUT RIV LB 14	SESUIT HBR E JTY DBN 3 WATCHING PROPERL 22/97 SESUIT HBR W JTY LT 2 WATCHING PROPERL 22/97 CONNECTICUT RIV LB 14 RELIGHTED	SESUIT HBR E JTY DBN 3 WATCHING PROPERLY 22/97 SESUIT HBR W JTY LT 2 WATCHING PROPERLY 22/97 CONNECTICUT RIV LB 14 RELIGHTED 12375

DISCREPANCIES (PRIVATE AIDS)

LLNR Name of Aid Status Chart BNM LNM affected Ref. Ref.

NONE THIS WEEK

DISCREPANCIES (PRIVATE AIDS) CORRECTED

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref

NONE THIS WEEK

III TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED This section contains temporary changes and corrections to Aids to Navigation for the current week. When aids are temporarily relocated for dredging, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY CHANGES

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref.

00000 WOODSHOLE OCEANOGRAFIC LB "ODAS" ESTABLISHED (Priv aid, See Sec IV) 13229 CG1-0273-97 23/97

00000 JAMES LONGSTREET ISO DANGER LB "WK" ESTABLISHED (Priv aid, See Sec IV) 13250 CG1-0277-97 23/97

00000 NANTUCKET SHOAL OCEAN LB "P" ESTABLISHED 13006 CG1-0179-97 23/97 00000 UPPER KENNEBEC RIVER BUOY 48A ESTABLISHED (See Sec IV) 13298 POR-

0041-97 23/97

TEMPORARY CHANGES CORRECTED

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref.

22665 CONNECTICUT RIV LB 26 WATCHING PROPERLY 12354 CG1-0264-97

22/97

22930 CONNECTICUT RIV LB 46 WATCHING PROPERLY 12354 CG1-0265-97

22/97

IV CHART CORRECTIONS This section conatains corrections to federal and private maintained Aids to Navigation, as well as NOS corrections.

ØØØØØØØØØØØØØØØØØ

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. The mariner must decide which Chart(s) to correct.

The following example explains the individual elements of a typical chart correction

The following	exampie e	xpiains the	e individual elements d	or a typical chart correction	on.
Chart	Chart	Edition	Last Local Notice	Horizontal	Source of
	edition	date	to Mariners	Datum Reference	Correction
Notice to Mari	ners /	/	/	/	/
13248 (15/93)	6 th ed. 09	/05/81 LA	AST LNM 42/85	NAD 83	(CG1)
` '	IASSACH	USETTS -	SEACOAST locat	ion	
Cl 69o51 17.1W	hange: F	og signal o	of Buoy PR to WHIS	ΓLE	41o36 12.1N
/		1			/
Corrective Object of corrective			Position (Degre	Position (Degrees, minutes, seconds	
and tenths)					
the Metric side Courses and b	immediate of the ch bearings a	art only. (7 re given in	Temp)indicates that the degrees clockwise from	dicates that the correction e chart correction action om 000 true. Bearings of pressed in nautical miles	is temporary in nature. light sectors are toward
QQQQQQQQQQ			ØØØØØØØØØØØØØØØ	70000000000000000000000000000000000000	ZQQQQQQQQQQQQQQ
12327 91th e	d., 04/19/9	97 LAST L	.NM 15/97 NAD 83		23/97

```
12327 91th ed., 04/19/97 LAST LNM 15/97 NAD 83
       NY - NJ - NEW YORK HARBOR - RARITAN BAY
       (NOS SILVER SPRING, MD)
       (New edition due to changes in hydrography and various general changes)
1:40,000/$14.00
```

Add Symbol for obstruction, depth unknown

40238'22.8"N 074203'06.0"W

12334 62nd ed., 11/16/96 LAST LNM 15/97 NAD 83 23/97 NY - NJ - NEW YORK HARBOR - UPPER BAY AND NARROWS - ANCHORAGE CHART (NOS SILVER SPRING, MD)

Add Symbol for obstruction, depth unknown 40238'22.8"N 074203'06.0"W

12350 55th ed., 06/24/95 LAST LNM 23/97 NAD 83 23/97 NEW YORK - JAMAICA BAY AND ROCKAWAY INLET (CGD01)

North Channel Buoy 31 from Relocate

(40238'38.8"N, 73250'22.7"W) to 40238'40.0"N

073250'23.6"W

13003 41st ed., 07/22/95 LAST LNM 21/97 NAD 83

23/97

CAPE SABLE TO CAPE HATTERAS (CGD01) Boston Approaches Lighted Whistle Buoy BD Change to FI (4) Y 20s 42208'15.4"N 069253'35.1"W (Supersedes LNM 20/97) 13006 29th ed., 03/22/97 LAST LNM 20/97 NAD 83 23/97 WEST QUODDY HEAD TO NEW YORK (NOS SILVER SPRING, MD) NOAA Data Lighted Buoy 44013 (ODAS) to FI (4) Y 20S PA 4221'30.0"N 070241'00.6"W (CGD01) Boston Approaches Lighted Whistle Buoy BD to FI (4) Y 20s 42208'15.4"N 069253'35.1"W (Supersedes LNM 21/97) 13009 27th ed., 08/17/96 LAST LNM 20/97 NAD 83 23/97 GULF OF MAINE AND GEORGE'S BANK (CGD01) Boston Approaches Lighted Whistle Buoy BD Change 42208'15.4"N 069253'35.1"W to FI (4) Y 20s (Supersedes LNM 20/97) 13200 30th ed., 10/26/96 LAST LNM 20/97 NAD 83 23/97 GEORGE'S BANK AND NANTUCKET SHOALS (CGD01) Boston Approaches Lighted Whistle Buoy BD Change to FI (4) Y 20s 42208'15.4"N 069253'35.1"W (Supersedes LNM 20/97) 13215 15th ed., 04/12/97 LAST LNM 15/97 NAD 83 23/97 BLOCK ISLAND SOUND - POINT JUDITH TO MONTAUK POINT (NOS SILVER SPRING, MD) (New edition due to changes in hydrography and various general changes) 1:40,000/\$14.00 13223 35th ed., 03/29/97 LAST LNM 13/97 NAD 83 23/97 NARRAGANSETT BAY INCLUDING NEWPORT HARBOR (NOS SILVER SPRING, MD) (New edition due to various general various) 1:20.000/\$14.00 13224 35th ed., 03/29/97 LAST LNM 13/97 NAD 83 23/97 PROVIDENCE RIVER AND HEAD OF NARRAGANSETT BAY (NOS SILVER SPRING, MD) (New edition due to changes in hydrography and various general changes) 1:20,000/\$14.00 13229 26th ed., 11/09/96 LAST LNM 14/97 NAD 83 23/97 (TEMP) SOUTH COAST OF CAPE COD AND BUZZARDS BAY (CGD01) Woodhole Temporary Oceanographic Add Lighted Buoy "ODAS", FI Y 4s, yellow (Priv maint) 41231'48.0"N

070238'24.0"W

13230 42nd ed., 11/02/96 LAST LNM 20/97 NAD 83 23/97 (TEMP) MA - BUZZARDS BAY (CGD01) Woodhole Temporary Oceanographic Lighted Buoy "ODAS", FI Y 4s, yellow (Priv maint) 41231'48.0"N 070238'24.0"W 13237 36th ed., 07/13/96 LAST LNM 10/97 NAD 83 23/97 (TEMP) NANTUCKET SOUND AND APPROACHES (CGD01) Woodhole Temporary Oceanographic Add Lighted Buoy "ODAS", FI Y 4s, yellow (Priv maint) 41231'48.0"N 070238'24.0"W 13246 32nd ed., 10/19/96 LAST LNM 20/97 NAD 83 23/97 (TEMP) MA - CAPE COD BAY (CGD01) ADD Isolated Danger Buoy "WK" FI (2) 5s, black/red 41249'52.8"N 070202'37.8"W 13246 32nd ed., 10/19/96 LAST LNM 23/97 NAD 83 23/97 MA - CAPE COD BAY (CGD01) Boston Approcahes Lighted Whistle Buoy BD Change to FI (4) Y 20s 42208'15.4"N 069253'35.1"W (Supersedes LNM 20/97) 13250 7th ed., 08/19/89 LAST LNM 13/97 NAD 83 23/97 (TEMP) WELLFLEET HARBOR (CGD01) ADD Isolated Danger Buoy "WK" FI (2) 5s, black/red 41249'52.8"N 070202'37.8"W 13260 35th ed., 01/25/97 LAST LNM 21/97 NAD 83 23/97 BAY OF FUNDY TO CAPE COD (NOS SILVER SPRING, MD) NOAA Data Lighted Buoy 44013 (ODAS) Change to FI (4) Y 20s PA 4221'30.0"N 070241'00.6"W Height of Light to 47 feet 44217'13.0"N 066²20'31.2"W (CGD01) Boston Approcahes Lighted Whistle Buoy BD to FI (4) Y 20s 42208'15.4"N 069253'35.1"W (Supersedes LNM 20/97) 13267 28th ed., 01/25/97 LAST LNM 16/97 NAD 83 23/97 MASSACHUSETTS BAY (NOS SILVER SPRING, MD) Add NOAA Data Lighted Buoy 44013 (ODAS), FI (4) Y 20s PA 42°21'30.0"N 070°241'00.6"W 13274 22nd ed., 03/15/97 LAST LNM 11/97 NAD 83 23/97 PORTSMOUTH HARBOR TO BOSTON HARBOR (NOS SILVER SPRING, MD) (New edition due to various general changes) 1:40.000/\$14.00 13288 36th ed., 01/18/97 LAST LNM 16/97 NAD 83 23/97

ME-MONHEGAN ISLAND TO CAPE ELIZABETH (NOS SILVER SPRING, MD) Delete Killick Stone Island buoy "2" 43255'59.0"N 069²25'03.0"W 13298 8th ed., 06/26/93 LAST LNM 23/96 NAD 83 23/97 (TEMP) COURTHOUSE POINT TO AUGUSTA (CGD01) Add Upper Kennebec River buoy 48A, red 44²14'57.2"N 069²46'04.1"W 13301 20th ed., 03/01/97 LAST LNM 51/96 NAD 83 23/97 MUSCONGUS BAY (NOS SILVER SPRING, MD) Killick Stone Island buoy "2" Delete 43255'59.0"N 069²25'03.0"W 13302 18th ed., 08/03/96 LAST LNM 15/97 NAD 83 23/97 PENOBSCOT BAY AND APPROACHES (CGD01) Relocate Halibut Rock Buoy 2B from (43259'00.6"N, 69202'58.8"W) to 43259'03.6"N 069²03'04.2"W

23/97

13303 11th ed., 07/06/91 LAST LNM 15/97 NAD 83

(CGD01)

APPROACHES TO PENOBSCOT BAY

Relocate Halibut Rock Buoy 2B from (43²59'00.6"N, 69²02'58.8"W) to 069²03'04.2"W

43259'03.6"N

V ADVANCE NOTICES This section contains advance notice of approved projects or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transitting these areas.

MA - GEORGES BANK AND NANTUCKET SHOALS - On or about 16 August 1997, Nantucket Shoals Lighted Horn Buoy N (Large Navigational Buoy) (LLNR 580) will be replaced with Nantucket Shoals Lighted Horn Buoy N (LLNR 580) showing Mo (A) W, passing light of FI W 4s, RACON (N), Horn, red and white vertical stripes and will be relocated to (PA) 40-35-00N, 069-00-00W.

Chart(s): 13200, 13003, 13006. 13009 LNM 23/97 (CGD1)

MA-SIPPICAN HARBOR-On or about June 16, 1997, Sippican Harbor Buoy 11 (LLNR 17165) will be discontinued. Sippican Harbor Buoy 13 (LLNR 17170) will be replaced with a private aid, green can, in the same position.

Chart(s): 13236 LNM 23/97 CGD1

VI PROPOSED CHANGES This section contains notice of non approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to: Commander, First Coast Guard District (oan), 408 Atlantic Avenue, Boston, MA 02110-3350, unless otherwise noted.

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

WATERWAY Closing Docket No. Ref. LNM

NONE THIS WEEK

VII GENERAL This section contains information of general concern to the mariner. Mariners are advised to use caution while transitting these areas.

FOR STANDARD MILITARY AND GENERAL SAFETY ZONES IN EFFECT SEE THE MONTHLY EDITION LNM 20/97

NY - UPPER BAY - The sunken anchor reported in LNM 16/97 in New York Upper Bay, Federal Anchorage 21C, has now been charted. Please see Section IV.

Chart(s) 12334 LNM 16/97 (CGD1)

BRIDGE SECTION

APPLICATIONS HAVE BEEN RECEIVED FOR COAST GUARD PERMITS FOR THE FOLLOWING BRIDGE CONSTRUCTION/RECONSTRUCTION PROJECTS:

BRIDGE WATERWAY MILE NOTICE# COMMENT PERIOD ENDS REF/LNM

Kittery Point Br. Spruce Creek NA PN-1-897 9 June 1997 20-97

Interested parties are requested to submit their views in writing, on the proposed bridge project, to the office of Commander (obr), First Coast Guard District, Bldg. 135A, Governors Island, NY, NY 10004-5073. Copies of Public Notices may also be obtained at this address.

MASSACHUSETTS - BEVERLY HARBOR - DANVERS RIVER - Channel Obstruction - The Beverly Harbormaster has reported an area of shallow water in the vicinity of the Old Rt 1A Bridge across the Danvers River at mile 0.0 between Beverly and Salem, MA. An area with only 3 feet at low tide has been observed. The Coast Guard is investigating this situation and will provide more information as it becomes available. Mariners are advised to exercise caution when transiting the area and contact the Beverly Harbormaster at (508) 921-6059 for further information. Chart 13275 LNM 23/97 (CGD1)

MASSACHUSETTS - NEWBURYPORT HARBOR AND PLUM ISLAND SOUND - PARKER RIVER/ROWLEY RIVER - Bridge Construction - The MBTA is replacing the railroad bridge at mile 3.0 over the Parker River and at mile 2.5 over the Rowley River. Construction will be ongoing between June 1997 through June 1998. All work will be performed from the existing bridge. Mariners are advised to exercise caution when transiting the area. Chart 13282 LNM 23/97 (CGD1)

VIII LIGHT LIST CORRECTIONS

(1) (2) (3) (4) (5) (6) (7) (8)

No. Name and location Position Characteristic Ht Rng Structure

Remarks

632 Buzzards Bay Temporary Remove from list.

15987 Lighted Horn Buoy B (LNB)

• 23/97

15987 Buzzards Bay Temporary

632 Lighted Horn Buoy B (LNB)

23/97

Remove from list.

MARINE EVENTS 1996/1997

Marine Events normally will be published only once. Please mark your calendars accordingly.

LOCATION DATE/S TIME EVENT/SPONSOR CHART

JUNE

NY-NJ-Raritan Bay	06/06 1730-2000	JY15 Adam/Eve Series, Race No. 1
-	Raritan Yacht Club	12331
NY-NJ-Raritan Bay	06/11 1800-2100	Wednesday Night Series, Race No. 4
	Raritan Yacht Club	12331
NY-NJ Raritan Bay	06/13 1730-2000	JY15 Summer Series Race No. 1
	Raritan Yacht Club	12331
NY-NJ Raritan Bay	06/15 1300-1600	Father's Day RacE
	Raritan Yacht Club	12331
NY-NJ Raritan Bay	06/18 1800-2100	Wednesday Night Series, Race No. 5
	Raritan Yacht Club	12331
NY-New York Yacht Cl	ub 06/18-21	1100-1700 New York Yacht Club 13223

MARINE EVENTS 1996/1997 (continued)

LOCATION DATE/S TIME EVENT/SPONSOR CHART

NY-NJ-Raritan Bay 06/20 2100-2330 Full Moon Series No. 1

Raritan Yacht Club 12331

NY-NJ Raritan Bay 06/20 1730-2000 JY15 Summer Series No. 2

Raritan Yacht Club 12331

NY-NJ Raritan Bay 06/21 1300-1600 Double Handed Series Race No. 2

Raritan Yacht Club 12331

MA-Gloucester, Ma.; Inner Hbr 06/21 0900-1200 International Dory Race Committee No Channel, Wright's Fish Co-P O Box 852; Gloucester, MA 01931-0852

to CG Station International Dory Races

NY-NJ Raritan Bay 06/22 1300-1600 Adam & Eve Race

Raritan Yacht Club 12331

NY-NJ Raritan Bay 06/25 1800-2100 Wednesday Night Series II, Race No. 1

Raritan Yacht Club 12331

NY-NJ Raritan Bay 06/27 1730-2000 JY 15 Summer Series, Race No. 3

Raritan Yacht Club 12331

RI-Block Island Sound 06/22-27 1000-1700 Storm Trisail Club 13217

Storm Trisail Club

NY-NJ Raritan Bay 06/28 1300-1600 Compton Series, Race No. 2

Raritan Yacht Club 12331

CT-Bridgeporport, CT Seaside Park 06/27 2000-2230 P. T. Barnum Foundation Inc., 1070

Main St; 12354, 12369

(Rain Date 06/28) Holiday Inn Ste 208; Bridgeport, CT 06604

The Barnum Festival Fireworks

NY-NJ Raritan Bay 06/29 1300-1600 Novice Race No. 1

Raritan Yacht Club 12331